

Corner originally set as a post in 1820 by John Hendricks with the following witnesses: 30" beech bearing north 74 degrees, thence east 29 links; and a 20" dogwood bearing south 83 degrees, thence west 25 links. (M.C. Atlas p. 10) A survey by Wm. P. Smith on June 24, 1890 indicates no stone or witnesses. (Warren Legal Book p. 43) Corner referenced by Wilcoxen on 9/10/75 and called a road nail over steel plate. Corner referenced by Gries on 8/29/88 and called a road nail over steel plate. Corner referenced by Kiste on 7/5/95 and called a road nail over steel plate. Corner referenced by Wilcoxen on 11/29/99 and called a road nail with washer over steel plate. Corner referenced by Wilcoxen on 6/8/04 and called a road nail with washer. Corner excavated by Wilcoxen on 8/11/08 and a 8" round plate was found 4" down. No other points were found. A #205 cast iron Harrison Monument was set in position of the steel plate.

DEE	1504030	
REF.	DISTANCE	DESCRIPTION
1.	40.56	Cut 'x' SW corner of inlet
2.	51.10'	Cut 'x' SW bolt of aluminum pole base
3.	50.20'	Cut 'x' NF bolt of aluminum pole base
4.	46.51'	Top nut of fire hydrant
5.	18.29'	Due W to SW corner of 34-16-4 (Harrison)
6.	53.75'	Mag nail w/bw F PwP#245-513 3"up